




The 5-Phase Stepping Driver

PMM-BA-5603-1 PMM-BA-5643-1

AC100V/115V
Full-step/half-step
(500 x 1 division) (500 x 2 divisions)

- Applicable motor



Characteristics

- **Flexible**

These drivers can drive various stepping motors of small to large capacities without adjustment for wide range uses.

- **Small size and high torque**

Dedicated ICs are mounted to realize the small size and high torque as a result of parts consolidation and high reliability.

- **Two types interface**

Two lineup types are:

Terminal block type :PMM-BA-5603-1

Connector type :PMM-BA-5643-1

Built-in function

- **Low-vibration control**

Our original control system employment enables a smooth and low-vibration operation.

- **Pulse input system selection function**

Either single or double input system can be selected by using dipswitches.

- **Operation current switchover function**

Stepping motor operation current ranging from the rated one to 40% can be set by using the rotary switch.

PM driver specifications

Item	PMM-BA-5603-1	PMM-BA-5643-1
Standard specifications Environment	Input source	Single phase AC100/115V+10, -15% 50/60Hz
	Source current	4A
	Operating ambient temperature	0 to +50°C
	Conservation temperature	-20 to +70°C
	Operating ambient humidity	35 to 85 % RH (no condensation)
	Conservation humidity	10 to 90 % RH (no condensation)
	Vibration resistance	0.5G Tested under the following conditions: Frequency range: 10 to 55 Hz, 0.5 G along the X, Y, and Z axes for 2 hours
	Impact resistance	No abnormality for the NDS-C-0110 Standard, Section 3.2.2, Division "C".
	Withstand voltage	No abnormality against an AC 1500 V application between the power input terminal and the cabinet for one minute.
Function	Insulation resistance	Minimum 10 MΩ when applying the DC 500 V Megger between the power input terminal and the cabinet.
	Weight	1.2kg
	Protection function	Against PM driver overheat
	Selection function	Automatic current reduction, excitation mode, pulse input system, operation current, and low vibration
I/O signals	LED Indicator	Power supply monitor, phase origin monitor, pulse monitor, and alarm monitor.
	Command pulse input signal	Photocoupler input system, input resistance 330 Ω Input signal voltage: "H" level: 4.0 to 5.5 V, "L" level: 0 to 0.5 V Maximum input frequency: 100 k pulses/s
	Power down input signal	Photocoupler input system, input resistance 330 Ω Input signal voltage: "H" level: 4.0 to 5.5 V, "L" level: 0 to 0.5 V
	Phase origin monitor output signal	Open collector output by photocoupler Output signal standard Vceo: Maximum 30 V, Ic: Maximum 5 mA
	Alarm output signal	Relay contact output (normal open) Contact capacity: Maximum 1 A at DC 24 V or maximum 0.5 A at AC 120 V


Standard combined stepping motor

Stepping motor dimensions	Stepping motor model number		Holding torque [N·m]	Rotor inertia [$\times 10^{-4}$ kg·m 2]	Weight [kg]	Page
	Single-axis shaft	Dual-axis shaft				
□42mm	103H5505-7040	103H5505-7010	0.127	0.03	0.23	Page 311
	103H5508-7040	103H5508-7010	0.176	0.053	0.28	
	103H5510-7040	103H5510-7010	0.255	0.065	0.37	
□50mm	103H6500-7041	103H6500-7011	0.235	0.057	0.38	Page 313
	103H6501-7041	103H6501-7011	0.39	0.105	0.44	
□60mm	103H7851-7051	103H7851-7021	0.65	0.275	0.6	Page 315
	103H7852-7051	103H7852-7021	0.98	0.4	0.78	
	103H7853-7051	103H7853-7021	1.86	0.84	1.36	
ø60mm	103H7521-7051	103H7521-7021	0.46	0.148	0.51	Page 317
	103H7522-7051	103H7522-7021	0.735	0.18	0.6	
	103H7523-7051	103H7523-7021	1.568	0.423	1.1	
ø86mm	103H8581-7041	103H8581-7011	2.06	1.45	1.5	Page 319
	103H8582-7041	103H8582-7011	4.02	2.9	2.5	
	103H8583-7041	103H8583-7011	6.17	4.4	3.5	
ø106mm	103H89582-7041	103H89582-7011	10.8	14.6	7	Page 321
	103H89583-7041	103H89583-7011	16	22	10.4	

• For the general specifications and dimensions of each stepping motor, refer to the reference pages.


Operation, connection, and function

- Each section name of the PM driver
PMM-BA-5603-1



- Internal power establishment (POW) Indicates that the internal power is established.
- Phase origin monitor (MON) Indicates that the excitation phase is at the origin (in the state when the power is turned ON).
- Input pulse monitor (PM) Indicates that the input pulse is applied.
- Alarm monitor(AL) Turns ON when the internal alarm circuit operates.
- Function selection dipswitch Functions can be selected according to (EX,F/R,SL,PD,PL,LFL,VE,TU)
- Operation current selection switch (RUN) Stepping motor current value during operation can be selected.
- Selection switch for low vibration (VA) Low-vibration operation and the stepping motor heat generation reduction can be performed.
- Terminal block (TB) I/O signals, the single-phase AC power source, and the stepping motor power cable are connected.

PMM-BA-5643-1




- Internal power establishment (POW) Indicates that the internal power is established.
- Phase origin monitor (MON) Indicates that the excitation phase is at the origin (in the state when the power is turned ON).
- Input pulse monitor (PM) Indicates that the input pulse is applied.
- Alarm monitor (AL) Turns ON when the internal alarm circuit operates.
- Function selection dipswitch Functions can be selected according to the specification.
- Operation current selection switch (RUN) Stepping motor current value during operation can be selected.
- Selection switch for low vibration (VA) Low-vibration operation and the stepping motor heat generation reduction can be performed.
- Connectors for I/O signal I/O signals are connected.
- Stepping output connector (CN2) The stepping motor power cable is connected.
- Power source input connector (CN3) Single-phase AC power source is connected.

Operation, connection, and function

External wiring diagram

PMM-BA-5603-1



Note 1)Use shielded twisted-pair cables.

Note 2)Either "double input system (CW and CCW)" or "single input system (CK and U/D)" can be selected by using the function selection switch F/R


Note 3)Refer to the following table when connecting the 103H785 □ type stepping motor:

Product	Terminal block silk/stepping motor connector pin number				
PM driver (TB)	BLACK	RED	ORANGE	YELLOW	BLUE
Stepping motor connector	1	4	3	2	5

Note 4)Ground the stepping motor flange section and the stepping motor fastening screw by fixing them together.

Use a single point grounding.

PMM-BA-5643-1



Note 1)Use shielded twisted-pair cables.

Note 2)Either "double input system (CW and CCW)" or "single input system (CK and U/D)" can be selected by using the function selection switch F/R

Note 3)Refer to the following table when connecting the 103H785 □ type stepping motor:


Product	Connector pin number				
PM driver (connector)	5	4	3	2	1
Stepping motor connector	1	4	3	2	5

Note 4)Ground the stepping motor flange section and the stepping motor fastening screw by fixing them together.

Use a single point grounding.

Operation, connection, and function

● Function selection dipswitch ---⑤



① EX (excitation system selection)

Excitation mode is selected.

EX	Energization system
ON	Half step (0.36°/pulse)
OFF	Full step (0.72°/pulse)

④ PD and PL (power down and power low selection)

The stepping motor windings current value at the power down signal input is selected.

PD	PL	Stepping motor current
ON	OFF	OA(power OFF)
OFF	ON	The current value (power low) using the stopping current adjustment control (STP)

⑤ LEL selection (Note)

This switch is not used.

Do not turn it ON.

⑥ VE and TU selection (Note)

This switch is not used.

Do not turn it OFF.

- Settings at the shipment are shown above.

- Turn OFF the PM driver power before changing switch settings to change the function selection dipswitch settings.

● Operation current selection switch (RUN) ---⑥

The operation current value of stepping motor can be selected.

Scale	0	1	2	3	4	5	6	7
Stepping motor current (A total)	3.0	2.9	2.8	2.6	2.5	2.4	2.3	2.2
Scale	8	9	A	B	C	D	E	F
Stepping motor current (A total)	2.1	1.9	1.8	1.7	1.6	1.5	1.3	1.2

- "0" is set at the shipment.

- 0.75 A/phase is set at scale 0.

● Low-vibration selection switch (VA) ---⑦

The vibration and the stepping motor heat generation can be reduced.

Scale	Function
9	Standard
3	Vibration reduction Motor heat generation reduction
2	
1	
0	

- "9" is set at the shipment.
Settings from 0 to 3 are valid.

- Sometimes the high-speed torque may decrease.

Operation, connection, and function

● I/O signal function ---8

Signal name (Abbreviation)	Silk print/Pin Number		Function
	Terminal block type	Connector type	
CW pulse input (CW)	CW+ CW-	A1 B1	When using double input system Drive pulse for the CW direction rotation is input.
Pulse column input (CK)	CK+ CK-	A1 B1	When using single input system Drive pulse train for the stepping motor rotation is input.
CCW pulse input (CCW)	CCW+ CCW-	A2 B2	When using double input system Drive pulse for the CCW direction rotation is input.
Rotation direction input (U/D)	U/D+ U/D-	A2 B2	The rotation direction signal of stepping motor is input for the single input system. Internal photocoupler ON CW direction Internal photocoupler OFF CCW direction
Power down input (PD)	PD+ PD-	A3 B3	Inputting the PD signal cuts OFF the current flowing through the stepping motor (turns OFF the power). (The power down input can be changed to the power low function by selecting dipswitches.) PD input signal ON (internal photocoupler ON) PD function enabled PD input signal OFF (internal photocoupler OFF) PD function disabled
Phase origin monitor output (MON)	-	A4 B4	It is turned ON when the excitation phase is at the origin (in the state when the power is turned ON) It is turned ON once per 10 pulses when setting to 2-division (full step). It is turned ON once per 20 pulses when setting to 1-division (half step).
Alarm output (AL)	AL1 AL2	A5 B5	The signal is externally output when one of several alarm circuits operates in the PM driver. At this time, the stepping motor is in the unexcited state.

- The terminal block type indicates "PMM-BA-5603-1" and the connector type indicates "PMM-BA-5643-1" in the table.
- The CW direction of stepping motor means the clockwise direction rotation as viewed from the output shaft side (flange side). The CCW direction means the counterclockwise direction rotation as viewed from the output shaft side (flange side).

● Connectors to be used


PMM-BA-5643-1

PM driver side		Applicable connector model number	Manufacturer
Used for	Model number		
I/O signals (CN1)	HIF3BD-10PA-2.54DS	Applicable socket :HIF3BD-10DA-2.54R	Hirose Electric Co., Ltd.
Stepping motor (CN2)	5274-05A	Applicable housing:5195-05 Applicable contact:5194PBTL	Molex Japan
AC power source (CN3)	5274-03A	Applicable housing:5195-03 Applicable contact:5194PBTL	Molex Japan

- The applicable connectors should be either prepared by the user or ordered from the optional connector set or connector cables (refer to Option in page 201).
- PMM-BA-5603-1 using the terminal block interface does not require connectors.


Operation, connection, and function

● Input circuit configuration (CW and CCW)



- Pulse duty is 50 % or less.
- When the peak value of the input signal is 5V, the external limit resistance R is 0Ω . If the peak value exceeds 5V, set the input current to approx. 15mA using the external limit resistance R.

Input signal specifications




Timing of the command pulse

• Double input system (CW and CCW)




- The internal photocoupler turns ON at the leading edge of the photocoupler "ON".
- When applying the pulse to CW, set the internal photocoupler on the CCW side to "OFF".
- When applying the pulse to CCW, set the internal photocoupler on the CW side to "OFF".

• Single input system (CK and U/D)



- The internal photocoupler turns ON at the leading edge of the CK photocoupler "ON".
- Before switching the U/D input signals, turn OFF the internal photocoupler on the CK side.


● Input circuit configuration (PD)



- When the peak value of the input signal is 5V, the external limit resistance R is 0Ω . If the peak value exceeds 5V, set the input current to approx. 15mA using the external limit resistance R.

Operation, connection, and function

● Output circuit configuration (MON and AL)



- Alarm output signal
Contact type: Relay contact output (normal open)
Contact capacity: Maximum 1 A at DC 24 V or maximum 0.5 A at AC 120 V
- Phase origin monitor output signal
Contact type: For open collector output by photocoupler
Contact capacity: Maximum 5 mA at DC 30 V
- Phase origin monitor output signal is compatible with PMM-BA-5643-1.
(There is no phase origin monitor output signal for PMM-BA-5603-1.)
- I/O connectors B4 and B5 of PMM-BA-5643-1 are common inside.

● Timing of the MON output (at full step)



- The internal photocoupler turns "ON" at [].

● State Indication (LED)

Indication	Color	Explanation
POW turns on.	Green	Internal power has been established.
MON turns on.	Green	Excitation phase is at the origin (the power is turned on). When 1-division is specified (full step), turns on once in 10 pulses. When 2-division is specified (half step), turns on once in 20 pulses.
PM turns on.	Green	Command pulse is input. Turns on for Approx. 100ms for every one pulse input.

● Timing of MON illumination (at full step)



- The internal photocoupler turns "ON" at [] and MON illuminates.



● Alarm Indication (LED)

Indication	Color	Explanation
AL turns on.	Red	The overheat protection alarm circuit of the internal device operates. The circuit operates when both the internal temperature of the PM driver and the ambient temperature become 80°C or more.



- Each alarm circuit operation turns on the alarm LED and cuts off the stepping motor current to result in the unexcited state. At the same time, the alarm output circuit photocoupler of I/O signal connector (CN1) turns ON and the signal is output externally. The alarm automatically stops to turn ON the stepping motor current when the internal semiconductor temperature becomes 80°C or less. Turn OFF the main power and try to radiate the generated heat by the forced-air-cooling of PM driver cabinet and so on before the automatic recovery from the alarm state when an alarm occurs.

Dimensions (Unit: mm)


PMM-BA-5603-1



PMM-BA-5643-1




Installation direction and position



- Install the PM driver vertically.
- As shown in the figure, fix the PM driver by using the M4 screws through fitting holes on the bottom surface of PM driver (no fitting metals are necessary).
- Use such screws that enter inside the drive equipment for maximum 7 mm.

Pulse rate-torque characteristics/pulse rate-source current characteristics

● 103H5505-70 □□ :100V




Source voltage: AC100V • Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=0.94 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)

- - - Source current($T_L=MAX$) - - - Source current($T_L=0$)

fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

● 103H5508-70 □□ :100V




Source voltage: AC100V • Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=0.94 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)

- - - Source current($T_L=MAX$) - - - Source current($T_L=0$)

fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

● 103H5510-70 □□ :100V




Source voltage: AC100V • Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=0.94 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)

- - - Source current($T_L=MAX$) - - - Source current($T_L=0$)

fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

● 103H6501-70 □□ :100V




Source voltage: AC100V • Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=0.94 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)

- - - Source current($T_L=MAX$) - - - Source current($T_L=0$)

fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

● 103H7851-70 □□ :100V



Source voltage: AC100V • Winding current: 0.75 A/phase


— Getaway torque($J_{L1}=2.6 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)

- - - Source current($T_L=MAX$) - - - Source current($T_L=0$)

fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

Pulse rate-torque characteristics/pulse rate-source current characteristics


●103H7852-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=2.6 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=MAX$) - - - Source current($T_L=0$)
 f_s : Maximum self-start frequency when not loaded ■ Full step ■ Half step


●103H7853-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=7.4 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=MAX$) - - - Source current($T_L=0$)
 f_s : Maximum self-start frequency when not loaded ■ Full step ■ Half step


●103H7521-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=0.94 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=MAX$) - - - Source current($T_L=0$)
 f_s : Maximum self-start frequency when not loaded ■ Full step ■ Half step


●103H7522-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=2.6 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=MAX$) - - - Source current($T_L=0$)
 f_s : Maximum self-start frequency when not loaded ■ Full step ■ Half step


●103H7523-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=7.4 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=MAX$) - - - Source current($T_L=0$)
 f_s : Maximum self-start frequency when not loaded ■ Full step ■ Half step

●103H8581-70 □□ :100V




Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($J_{L1}=7.4 \times 10^{-4} \text{ kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=MAX$) - - - Source current($T_L=0$)
 f_s : Maximum self-start frequency when not loaded ■ Full step ■ Half step

Pulse rate-torque characteristics/pulse rate-source current characteristics


●103H8582-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($JL1=15.1 \times 10^{-4} \text{kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=\text{MAX}$) - - - Source current($T_L=0$)
 fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step


●103H8583-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($JL1=44 \times 10^{-4} \text{kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=\text{MAX}$) - - - Source current($T_L=0$)
 fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step


●103H89582-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($JL1=44 \times 10^{-4} \text{kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=\text{MAX}$) - - - Source current($T_L=0$)
 fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

●103H89583-70 □□ :100V



Source voltage: AC100V · Winding current: 0.75 A/phase

— Getaway torque($JL1=44 \times 10^{-4} \text{kg}\cdot\text{m}^2$ using the rubber coupling)
 - - - Source current($T_L=\text{MAX}$) - - - Source current($T_L=0$)
 fs: Maximum self-start frequency when not loaded ■ Full step ■ Half step

Option

PMM-BA-5643-1

● Connector set

Model number	Used for	Set content	Combination stepping motor model number
PM-AP-049	I/O signal (CN1)	Applicable socket:HIF3BA-10DA-2.54R	Type 103H785 □
	Power source (CN3)	Applicable housing:5195-03 Applicable contact:5194PBTL	
	Stepping motor (CN2)	Applicable housing:5195-05 Applicable contact:5194PBTL Applicable housing:VHR-5N Applicable contact:SVH-21T-P1.1	
PM-AP-035	I/O signal (CN1)	Applicable socket:HIF3BA-10DA-2.54R	Type 103H55 □□ 103H650 □ 103H752 □ 103H858 □ 103H8958 □
	Power source (CN3)	Applicable housing:5195-03 Applicable contact:5194PBTL	
	Stepping motor (CN2)	Applicable housing:5195-05 Applicable contact:5194PBTL	

● Connector cable

Model number	Application
PM-C10S0100-03	Connector cable for I/O signals (CN1)
PM-C05M0100-□□	Connector cable for stepping motors (CN2)
PM-C03P0100-01	Connector cable for AC power source (CN3)

□□ are spaces to be filled by the serial number 05 or 06
(refer to Supplement table 1).

- The connector cable is a 1-meter cable assembled with the connector.

Applicable connector cable		
CN1	CN2	CN3
Cable 2	Cable 3 or 4	Cable 1

PMM-BA-5603-1

● Terminal block cover


Model number	Quantity
PM-AP-020	One

Stepping motor cable model number (Supplement table 1)


Serial No.	Stepping motor model number
05	103H5505-70 □□
	103H5508-70 □□
	103H5510-70 □□
	103H6500-70 □□
	103H6501-70 □□
	103H7521-70 □□
	103H7522-70 □□
	103H7523-70 □□
	103H8581-70 □□
	103H8582-70 □□
	103H8583-70 □□
	103H89582-70 □□
	103H89583-70 □□
06	103H7851-70 □□
	103H7852-70 □□
	103H7853-70 □□

Option


● Cable 1 (power source cable CN3)



● Cable 2 (I/O signal cable CN1)



● Cable 3 (stepping motor extension cable 1 CN2)



● Cable 4 (stepping motor extension cable 2 CN2)

